



PRODUCT ALERT

Alert: Some 2012 BMW vehicle models were released with a plastic oil module which requires NAPA part number 7292, and others of the same year, make, model, and engine may be equipped with an aluminum oil module which requires part number NAPA 107509.

**FILTER SELECTION MUST BE BASED ON THE OIL MODULE.
USE OF THE INCORRECT FILTER WILL RESULT IN ENGINE DAMAGE.**

7292/Plastic Module



BMW OES Filter

11 42 7 634 291

11 42 7 634 292

107509/Aluminum Module



BMW OES Filter

11 42 7 640 862

Affected models Include but are not limited to:

ActiveHybrid 5.30L, Z4 2.0L, 328i 2.0L, 528i 2.0L, X1 2.0L, 528i xDrive 2.0L

As a reminder, it has always been, and remains our recommendation that the selection of a replacement filter be conducted using only the most current application information available. In today's cataloging, the electronic (i.e. internet, interactive electronic) would be the most current application information available. For questions or more information, please contact your local NAPA Filter District Manager or call Product Information at 1.800.949.6698